

Meeting 4 with BuSha
10/10/14

- (1) Measuring and sensors:
 - a. Temperature → infrared
 - i. Why infrared over thermistor?
 - b. Heart Rate → IR diode and light sensor
 - c. Acceleration (Impact Forces)
 - i. Cost-benefit analysis between different accelerometers
 - ii. Why are we placing them where we are placing them
 - d. Hydration → Galvanic skin response
 - i. Feasibility?
 - e. Start dividing sensors among team members
- (2) Ordering Parts
 - a. Sooner the better
- (3) List of what everyone is doing