

Meeting with BuSha
10/15/14

(1) Responsibilities

- a. Programming – Rob and Aileen
- b. Temperature – Rob
- c. Hydration – Jess
- d. 3D Printing – Anasha

(2) Sensor Selection

- a. Accelerometer → triple axis accelerometer
- b. Temperature → TMP006 Thermopile
- c. Heart Rate → Pulse Oximeter

(3) Power Requirements

- a. 9 V battery